DOOSAN Document Transmittal

Upper Trishuli-1 HEP (216MW)

Date	DT No.:	SHEET
2022-05-01	UT1-HEP-DHI-PC-D-0028	1 OF 1

DOOSAN NEPAL BRANCH OFFICE	Address & Contact No. : Four Square Building, Naxal, Kathmandu, Nepal (P.O Box : 1387) + 977 1 692 3014	Project No. H20002	DOCUMENT DISPATCHED BY Courier Service ☐ Messenger ☐ Post-Air Freight ☐ Document System or E-mail ■ By hand ■
DOCUMENT DISTRIBUTION	■ POWER CHINA (Subcontractor) ☐ Doosan's Site Office		
SUBJECT	Review Note RN-0119_Excavation and support drawing of desander basin		

S. N.	REVIEW NOTE NO.	REVIEW STATUS	DWG. / DOC. NO.	REV.	DWG. TITLE / DOC. DESCRIPTION	REMARK
1	RN-0119	RR	UT1-C-030-CVL-DG-52002	0A	Excavation and support drawing of desander basin	
2						
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						

Received by :

Date :

Legend of Review Status
A : APPROVED
AN : APPROVED AS NOTED
RR : RETURN FOR RESUBMISSION
FI : FOR INFORMATION

DHI STAMP

Doosan Heavy Industries & Construction Co., Ltd. DOOSAN Branch Office Nepal

Issued by DHI

Youngsoo Son

Project Manager

Email: youngsoo.son@doosan.com
Doosan Heavy Industries & Construction Co., Ltd.

Discipline : Civil

UPPER TRISHULI-1 HEP (216MW)

Client	**Nepal Water and Energy Development Company Private Limited**
Owner's Engineer	**Tractebel Engineering GmbH / Jade Consult**

REVIEW NOTE

Contractor	**Doosan Enerbility**		
Title of the Document	Excavation and support drawing of desander basin		
Document No.	UT1-C-030-CVL-DG-52002	Revision	0A
Date of Documents	16.04.2022	Received Date	26.04.2022
Transmittal Form No.	UT1-HEP-DHI-D-0215		
Previous Review Date/Status	N/A	Prev. Review Note No.	N/A
Review Note No.	**RN-0119**	**Present Review Date**	**01.05.2022**
		Present Review Status	**RR**

A: Approved AN: Approved as Noted RR: Returned for Resubmission FI: For Information, only.

Comments

1. The physical hydraulic model test report for the Desander, which shall confirm the dimensions of the desander has been reviewed by OE and has been rejected for resubmission with review note RN-0117, dated 30/04/2022.
2. The layout drawings of the Desander have been reviewed by OE and have been rejected for resubmission with review note RN-0019, dated 20/10/2021.
3. No detailed geological information for the location of the Desander is available.
4. The respective rock stability analysis of the Desander is not available.

DISCLAIMER

Any approval will not release the Contractor from any of his obligations under the Contract.

Sebastian Beck, Chief Design Engineer